10-168

11/81

State Historic Preservation Officer

MAGI # 0439062404 UNITED STATES DEPARTMENT OF THE INTERIOR

Form Approved OMB No. 42-R1765

B-3906

NATIONAL PARK SERVICE Washington D.C. 20240

HISTORIC PRESERVATION CERTIFICATION APPLICATION—PART 1

Instructions: Applicant should read the instructions carefully before completing application. No certification may be made unless a completed application form has been received. Use typewriter or print clearly in dark ink to complete the application form. If additional space is needed to complete Part 1, use the reverse side or a separate plain sheet of paper clearly indicating the owner's name and mailing address. Part 1 of this application may be completed and sent to the appropriate State Historic Preservation Officer at anytime during the year.

PART	1 EVALUATION	ON OF SIGN	IFICANCE			
	of property: 639 N					· · · · · · · · · · · · · · · · · · ·
	ss of property: 639					
				County	State Md.	Zip Code _21230
Check EXcert	here if request is for: ification (structure con ertification (structure of	tributes to signific oes not contribute	ance of the distric	et)		
Statem The fac Dri Statem The and Del two Date of	ade is cover ve. There is sent of Significance: house deriv architectur ight general and a half construction (if know	photograph required two and one ed with for also a large with other ly. The so story hous circa 1850 of the country of the cou	me half stormstone, ayer of formstone, ayer of formstone, ayer of formstone are houses outh side ses, exceptions of the property of the proper	ory masonry relocated on the rmstone cover: from its simmon Melvin Drivof Melvin Driv	e south siding the bas ilarily of ive and in ve is made ses that ar	e of Melvin e (continued) construction Ridgely's up of e three (con't)
Street	Wheaton Pla	za Office	Building	North, Suite	403	•
City _	Wheaton					Zip Code 20902
Teleph	one number (during d	av): Area Code _2	01-946-37	60 (Wheaton)	301-792-401	9 (Baltimore)
	\sim					e property described above.
Signature Social Secur	Jay T. Fren	ch er Identification Nu	umber			Date 4/21/8)
For office us	e only		MANAGEMENT AND ADDRESS.	GERBARO SENDICIA SILOSSI	2 Ur and Constitutions	AND THE PROPERTY OF THE PARTY O
	e described above is inc r of the district.	luded within the bo	undaries of a Regi	stered Historic District an	d contributes	does not contribute to
structure inated to	e □ appears □ does the National Register	not appear to mee	t National Register Department of th	Criteria for Evaluation (3 ne Interior procedures (3	6 CFR 60.6) and 6 CRF 60).	will likely will not be
will likely and appropriate and certification	will not be nomi	nated to the Natio	onal Register in to the character	ear to meet National Regi accord with Department of said district or 🗆 w	t of the Interior provided likely in will no	ocedures (36 CFR 60).
Signature	TOV.	/ 5 -		\$2		Date D

CONTINUATION SHEET - 639 MELVIN DRIVE

HISTORIC PRESERVATION CERTIFICATION APPLICATION - PART 1

- facade of the front steps. The sills and lentles are wood and the dormer roof has been covered with shingles. There is no chimney. The rear facade has substantially deteriorated. Generally, the window sashes, doors and external wall curtains are in gross disrepair.
- 3. stories. The absence of ornate trim, decorative moldings and marble sills or steps is characteristic of the type of houses located on the small street of Melvin Drive behind the more expensive and ornate houses on Washington Boulevard. The alternating patterns of architecture on adjacent streets reflects the historic character and significance of Ridgely's Delight. The Ridgely's Delight neighborhood during the 1840's and 1850's was a socially and economically mixed neighborhood with both blue collar workers, who were employed in the nearby heavy industrial area, and professionals such as doctors and dentists employed at the University of Maryland Hospital several blocks to the north which was founded in 1812.

SEE PHOTOGRAPHS A AND B FOR STREET SCENES.




OTO A-Historic Preservation Certification Application - rt 1 - Street Scene looking east. 639 Melvin Drive.




PHOTO B-Hist.Pres.Cert.Applctn.-Part 1-639 Melvin Drive Street scene-looking west.



PHOTO 1-639 Melvin Dr.-His.Pres.Cert. Application-Part 2-Front facade.



MOTO 2 B - Hist.Pres.Cert.Applctn.-Part 2- 639 Melvin Dr. Door-second floor.






PHOTO 2A- Hist.Pres.Cert.Applctn.Part 2 639 Melvin Drive-Rear dormer on third floor (casings and moldings).

B-3906 639 Melvin Drive Block 685A Lot 083 Baltimore City Baltimore West Quad.

